

CASE STUDY



At a Glance: Market: Health Care

Location: Texas

Application:

Cameras placed in the nursing home for safety and to monitor patients

Case Study: Nursing Home Chooses LTS HD-TVI Solution

Introduction

Nursing homes help improve the quality of life for individuals with long term health conditions or disabilities. A large nursing home in Texas with more than 200 residents had a dire need for video solutions. The home's staff and doctors heavily rely on video security beyond basic needs. They use it to monitor patients, especially since another wing of the home is being built.

Challenge

The original building was constructed in the early 1970's. It was remodeled and expanded numerous times since. Attics and crawl spaces were not necessarily connected during any

marketing@LTSecurityinc.com I LTSecurityinc.com

Disclaimer: The information contained in this case study is to be used only as a case study reference for learning material purposes. Optional formulated by author are intended to protect companies and its names and does not necessarily reflect the views of LTS. For more information on terms of use, please contact <u>marketing@LTSecurityinc.com</u>



CASE STUDY

of the additions. More than a quarter of the cables were over 400 feet, some were as long as 750 feet.

Solution

Since the project had a fixed budget, the affordability and capabilities of HD-TVI allowed them to achieve all of their goals without compromising quality or coverage. Three Platinum Enterprise Level 16 Channel HD-TVI DVR 1.5U, LTD8416T-ST, were installed along with seven Samsung 37" HD monitors, and 40 HD-TVI 1080P cameras. They needed 12 HD eco-Platinum HD-TVI Bullet Cameras, CMHR9422, for outdoors, and 28 HD eco-Platinum HD-TVI Turret Cameras, CMHT2722, were placed indoors.







Featured Products:

(CMHT2722) eco-Platinum HD-TVI Turret Camera 2.1MP

(LTD8416T-ST) Platinum Enterprise Level 16 Channel HD-TVI DVR 1.5U

(CMHR9422) eco-Platinum HD-TVI Bullet Camera 2.1MP

Results

There was enough coverage to suffice the new wing being built and also upgrade their old analog system with high definition coverage. The extra wiring was quite a challenge but at the end of the day, the nursing home was satisfied and 14 locations will be using the same system.

marketing@LTSecurityinc.com I LTSecurityinc.com

Disclaimer: The information contained in this case study is to be used only as a case study reference for learning material purposes. Optional formulated by author are intended to protect companies and its names and does not necessarily reflect the views of LTS. For more information on terms of use, please contact <u>marketing@LTSecurityinc.com</u>